

RECOMMENDED CARES IN CASE OF STOPS

PERIOD	> 1 hour (during shift)	Overnight	Over weekend	≤ 2 weeks	> 2 weeks
Shutdown	Dry wipe	Dry wipe	Short prime (2 secs)	Short prime (2 secs)	Flush ink from system
	+	+	+	+	+
	Protect heads from sunlight	Power off	Dry wipe	Dry wipe	Dry wipe
	+	+	+	+	+
	Power off	Cap heads (recommended)/protect heads from direct strong lights)	Power off	Power off	Power off
				+	+
				Cap heads	Cap heads
Start-up	Power on	Remove caps	Remove caps	Remove caps	Remove caps
	+	+	+	+	+
	Clean* (as required)	Power on	Power on	power on	power on
		+	+	+	+
		Clean* (as required)	Clean* (as required)	Long prime (5 secs)	purge back to ink
				+	+
				Clean* (as required)	Clean* (as required)

*Must avoid dust or other particles in the nozzle part for a long time

ADDITIONAL RECOMMENDATIONS:

- | | |
|-------------|---|
| AS REQUIRED | Ink short purge » Dry wipe » Inspect |
| DAILY | Dry wipe » Ink long purge » Dry wipe » Inspect |
| WEEKLY | (as daily) » Repeat if necessary » Inspect » Print test message |

In case of finding clogged/blocked nozzles, REDEMAC could perform deeper cares.



SOINS RECOMMANDÉS EN CAS D'ARRÊTS

PÉRIODE	≥ 1 heure (pendant le quart de travail)	Pendant la nuit	Week-end	≤ 2 semaines	> 2 semaines
Shutdown	Chiffon sec	Chiffon sec	Purge court (2 sec)	Purge court (2 sec)	Enlever l'encre du système
	+	+	+	+	+
	Protéger les têtes des rayons du soleil	Mise hors tension	Chiffon sec	Chiffon sec	Chiffon sec
	+	+	+	+	+
		Capuchon des têtes (recommandé) / protéger les têtes des rayons de lumière forte			
	Mise hors tension		Mise hors tension	Mise hors tension	Mise hors tension
				+	+
Mise en service				capuchons de têtes	capuchons de têtes
	Allumer	Retirer les capuchons	Retirer les capuchons	Retirer les capuchons	Retirer les capuchons
	+	+	+	+	+
	Nettoyer * (au besoin)	Allumer	Allumer	allumer	allumer
		+	+	+	+
		Nettoyer * (au besoin)	Nettoyer * (au besoin)	Purge prolongée (5 secondes)	purge longue
				+	+
				Nettoyer * (au besoin)	Nettoyer * (au besoin)

* On doit éviter la poussière ou autres particules dans la buse pour une longue période.

RECOMMANDATIONS SUPPLÉMENTAIRES :

SELON LES BESOINS purge d'encre courte » Chiffon sec » inspecter

TOUS LES JOURS Chiffon sec » purge d'encre longue » chiffon sec » inspecter

HEBDOMADAIRE (comme tous les jours) » Répétez si nécessaire » inspecter » imprimer le message de test

En cas de trouver de points bouchés/bloqués, REDEMAC pourrait accomplir des soins plus profonds.

